



This survey was performed at the request of the LaPorte Group for a possible pending

The Title Report describes the area to be purchased. Underground utilities are not included, but

Checker Auto Survey by Great Basin) ie. N 00°36'55" W 2657.08' measured from the Northwest corner of Section 22 (Alum. Cap) to the West 1/4 Corner of said section (Carbon County Alum.Cap.); said cap being uncovered and matching for distance as per the aforesaid

was hole matching the location of the described Brass Washer as set in that survey. Also found at the Northwest corner of the Parcel was a hole, circled by paint, also matching in location. Uncovered at the Southeast corner of this Exception parcel was Great Basin's 5/8" Rebar/Cap; and likewise uncovered at the Southwest corner of the parcel was a 5/8" rebar without a cap; all

Engineering and Land Surveying. These corners were either found or set, with the front corner along Main Street matching exactly to the back of sidewalk. This boundary follows the wash to the Southeast corner of Lot 11 as recorded. Also found alonf the South line 58' West, was

Thence continuing West approximately 104' lies a Rebar/Cap (PLS PE-145656) marking the parcel boundary line. This distance exceeds the record as per the deed in the title report by about 9'. Additional research has revealed that this cap does not match either the West or East deed line

The found caps found along the South line of the Empire Survey, line up approximately along the 40 Acre line and are the best evidence of where this 1/6th sectional line has been placed and accepted. This line projected to the East, as shown on the survey, intersects with and represents the position of Northeast 1/4 Northwest 1/4 (1/6th corner). See sectional breakdown

Deeds were traced as per record and set parallel to sectional lines & 16th lines as per the practice in this area. The results match very closely with the survey performed by Arthur LeBron

Even though a deed gap appears on record, along the south side 2nd South Street, on the ground the opposite is found. There is an approximate 10' Encroachment in the North-South

This is attributed to the old city block survey, being extended Easterly across the Section lines of Section 22. (Section 22 deeds not being directly tied to the old city block surveys.) In any

event, the fence lines have been in place an perpetuate for a number of years, and represent lines of possessions. Reference points have been set indicating the amount and direction or error

portion of the property. Fence lines, barns and stall enchroach by the same 10' approximately.

Title to remove title issues and to provide a legal description for the aforementioned Eastgate

FEMA FLOOD ZONE X AREAS DETERMINED TO BE OUTSIDE 500 YEAR

ACTUAL SETBACK SUBJECT SUBDIVISION DESIGN REVIEW. PROPERTY AND REFERENCE CORNERS SET PRIOR TO TITLE REVISIONS

SCALE: DATE: DRAWN BY: SURVEY BY: CHECKED BY: JOB #: R- 12-012-H1 SURVEYED ON THE GROUND BETWEEN 2-22 - MAR. 5



FAX: (801) 606-2752

* SURVEYING

1260 EAST MAIN STREET PRICE CITY, UTAH

1260 EAST MAIN STREET

PRICE CITY, UTAH 84501

SHEET 2 OF 2 JUNE 6, 2012 SHEET 2